

SOLID CAST 606, Clear Doming Epoxy Resin

Solid Cast 606 is a low viscosity, cycloaliphatic epoxy resin system offering a long pot life and extended working time. The cured system has excellent clarity and colour retention. It is ideally suited for the production of clear castings, electrical encapsulation and badge coating. The system can be coloured by the addition of pigments and dyes to produce a broad range of coloured items.

Liquid Properties	Part A	Part B	Mixed
Colour	Clear liquid	Clear liquid	Clear Liquid
Viscosity cps@ 25°C	1500	120	
Mix Ratio by Weight	3	1	
Mixed viscosity cps @ 25°C			600-800
Pot Life 150g min@ 25°C			60

Typical Physical Properties

Hardness Shore D	85
Tensile Strength psi	10,200
Tensile elongation %	6.5
Refractive Index	1.48

Mixing.

Condition the material at 18-23°C.

With epoxies the larger the mass the shorter the potlife of the mix, only mix the amount of product that can be used within the potlife.

Accurately measure out Part A and Part B by weight into clean containers.

Add the Part B to the Part A and mix using a power stirrer operating at 15-250 rpm for 2-3 minutes. Scrape the sides and bottom of the mixing container, with a flat edged scraper, to incorporate any unmixed material clinging to the sides and bottom of the container.

Mix for a further minute until the material is uniform in colour and free from streaks.

Take care to keep the mixing blade fully immersed in the mix to avoid incorporating air.

Immediately pour the mixed material into the mould, pouring from one end of the mould in a thin stream. Vibrating the mould will help in bringing any air bubbles, that were incorporated into the mix, to the surface. When badge coating set the item to be coated on a perfectly level surface and pour the liquid so that it domes over the surface and is retained by the edges of the object.

Small bubbles trapped during pouring can be pricked with a pin or removed by gently blowing warm air over the surface.

Curing

This product must be heat cured to achieve full physical properties.

Allow the item to cure for 6-8hrs at room temperature then postcure for 4-6 hours at 60-70°C.

Demoulding time of cast items is dependent on the thickness of the cast item.

Health and Safety.

Avoid contact with skin and eyes. Wear gloves and safety glasses when using this product.

Use with adequate ventilation.

A detailed Material Safety Data Sheet is available for this product.